## IMPORTANT INFORMATION ABOUT YOUR DRINKING WATER

Triggered Source Monitoring and Reporting Violation: Groundwater Rule

Bethel Ash WSC Waters Edge Plant / PWS ID 1070251 failed to collect the required number of triggered source bacteriological samples for fecal indicator monitoring of the groundwater system during April/2024. This monitoring is required by the Texas Commission on Environmental Quality's "Drinking Water Standards" and the federal "Safe Drinking Water Act," Public Law 95-523.

Triggered source samples are used to monitor water quality and indicate if the water is free of fecal indicator bacteria. Following a positive routine total coliform result in our distribution system, our water system is required to submit one triggered source sample for every active groundwater well source. Failure to collect all required triggered source samples is a violation of the monitoring requirements and we are required to notify you of this violation.

## What should I do?

There is nothing you need to do at this time.

What is being done?

Bethel Ash WSC has submitted the required repeat samples and one raw water sample. The Waters Edge Plant TX1070251 has reached compliance by the Texas Commission on Environmental Quality's "Drinking Water Standards" and the federal "Safe Drinking Water Act," Public Law 95-523.

For more information, please contact <u>Karla Tharp</u> at <u>(903) 675-8466</u> or you may contact us at our email: baw@bethelashwater.com.

This notice is being sent to you by Bethel Ash WSC. Public Water System Number: TX1070251

Date Distributed: 08/01/2024